Technical Booklet

1. LG Service News

- Introducing LGRepair.com Website
- Safety Check List and Safe Repair instructions for R600a Sealed System Repair

2. LG SVC Tips

- How to resolve UE Error for WT6105CW (No LCD Display Model)
- How to service when "Power On but Won't Run or Not Start"
- Yoder Loop Leak Protocol and Testing

3. Service Bulletins

LG Electronics Alabama, Inc. 2023. 09




<u>Contents</u>

1. LG Service News	
- Introducing LGRepair.com Website(No Cool, Ice Water, Error Code, Test Mode)	Page. 2
- Safety Check List and Safe Repair instructions for R600a Sealed System Repair	Page. 3
2. LG SVC Tips	
- UE Error for WT6105CW	Page. 5
- How to service when "Power On but Won't Run or Not Start"	Page. 6
- Yoder Loop Leak Protocol and Testing	Page. 7
3. SVC Bulletin – Refrigerator	
3.1. [Parts] Air filter cover part standardization (Released date: 8/31/23)	Page. 12
4. SVC Bulletin – Washing Machine	
4.1. [SVC Guide] 24inch/27inch Dryer Roller (Released date: 7/17/23)	Page. 16
5. SVC Bulletin – Dishwasher	
5.1. [SVC Guide] IE Error Check and Repair guide(Released date: 7/24/23)	Page. 19
6. SVC Bulletin – Cooking(Gas Oven)	
6.1. [Parts] SKSDR480SIS/GS Water tank and steam heater proactive SVC guide (Released date: 6/9/23)	Page. 24
6.2. [SVC Guide] Replace the cooktop burner orifices(nozzles) (Released date: 1/20/23)	Page. 28
7. SVC Bulletin – TV	
7.1. [Parts] No video or TV guide Information doesn't automatically power off (OLED**M3) (Released date: 6/23/23) * The information is subject to change or update without notice.	Page. 32

Dear Valued Service Partners,

Over the past 6 months LG has launched many new resources for technicians. These resources are located at on the LG Technician Portal at <u>LGRepair.Com</u>. From No Cool Troubleshooting to instructions on how to enter Test Modes, visit <u>LGRepair.Com</u> and try out LG's latest resources for technicians! See below for some of the new offerings:



Dear Valued Service Partners,

In 2019, LG (and other manufacturers) began using R600a refrigerant in refrigeration products. Since most LG refrigerators now have this new refrigerant, repair volume as well as reclaims have been steadily increasing. Please see below for the safety checklist and repair instructions for R600a sealed system repair

Safety Check List

- 1. Check which refrigerant is used (R134a or R600a).
- 2. Use a combustible gas leak detector. If flammable refrigerant is detected, immediately ventilate. (Caution : do NOT use leak detectors with an arc or spark module to check for leaks)
- 3. Check the refrigerant used for refrigerator and use appropriate PPE for safety.
- 4. Ensure a dry-powder fire extinguisher rated for Class B fires is accessible on site.
- 5. Utilize a tubing cutter, not a torch or other heated surface tool due to flammable refrigerants.
- 6. Conduct all servicing in a well-ventilated area.
 - Whenever possible, open a window, door or other means to ventilate the area
 - The area should be free of open flame or burning materials
 - Maintain a safe zone around the appliance during service work to prevent ignition sources

1600a Se	aled Repa	air Basic	Tools				
Sparkless Vacuum Pump	Gas Leak Detector	Fire Extinguisher (dry-powder, Type B)	Refrigerant Recovery Bag (Vulcan)	Lokring Tool	Lokring Tool Jaw (2EA)	3 Way Valve Jig	R600a
				1	4 a -	CCCC	

Safe repair instructions for R600a sealed system repair

Please read the following instructions and differences between R134a and R600a repair carefully prior to R600s sealed system repair. There are special tools required for R600a sealed system repair, so it is very important to use the proper tools for your safety.

Steps	R134a	R600a					
Prepare	Have all tools ready for work	Ensure that the work area is well ventilated					
	Completely remo	ove refrigerant					
Refrigerant Removal	Using a certified recovery Machine and a recovery cylinder	Using a refrigerant bag					
Cutting	Do not use a torch to remove p	ipes, use a tubing cutter					
		Measure each pipe diameter to select Lokring size					
		Assemble Lokring w/ Lokring tool, jaws & Lokprep					
		Check gas leakage on Lokring connectors					
Connecting	Use either torch or Lokring	Lokring Lokring Lokprep Gas detector hand tool jaws					
Vacuum work	Use standard or sparkless vacuum pump	Use sparkless vacuum pump					
Recharging	Measure the R134a refrigerant amount with scale and recharge * Amount Tolerance : -3g ~ +3g	Use the exact amount of R600a required for the unit <u>* Amount Tolerance : -3g ~ +1g</u>					

Repair steps comparison

2. LG SVC Tips - UE Error Code: WT6105CW (No LCD Display Model)


Unbalanced Error Code (UE Error)

Cause #1: The unit is not properly leveled. \rightarrow Level the unit making sure the drum is centered properly.

Cause #2: The load is too small. \rightarrow Add additional items to allow the washer to balance the load.

Cause #3: Heavy articles are mixed with lighter items. \rightarrow Always try to wash articles of somewhat similar weight.

Cause #4: The load is out of balance. \rightarrow Manually redistribute the load if articles have become tangled.



UE Error: Wash/Rinse/Spin and Extra Rinse LED blinking

If you want to know more error codes for this model, please visit to the below site. You can check all error codes.

https://lgerrorcodes.com/toploadpanel_2/

How to service when *"Power On but Won't Run or Not Start"*

This letter is to inform the correct SVC guide for LG Dryer

There are several reclaim cases because technicians are replacing incorrect parts when the "Door Switch" is the root cause.

Unnecessary PCB replacements have been increased due to door switch.

Please refer the below SVC steps to avoid reclaim cases when "Power On But Won't Run or Not Starting".

- Symptom: Power On But Won't Run or Not Start
- SVC Instruction : Most cases could be resolved by Step 1 ~ 3 Step, otherwise move to Step 4 and 5
 - Step 1) Check "Child Lock" on \rightarrow "Child Lock" Off

Step 2) Check if the door is shut properly \rightarrow Clothes Interference, Incorrect Door Reversal

Step 3) Check "Door Switch" \rightarrow Replace with a new "Door Switch" if resistance values are not met

Door Switch	Door Condition	Measurement Points	Good Resistance Value
	Door	1) Terminal: COM-NC (1-3)	<1Ω
	Open	2) Terminal: COM-NO (1-2)	≒∞
2 2 1	Door	1) Terminal: COM-NC (1-3)	≒∞
3 2 1	Close	2) Terminal: COM-NO (1-2)	<1Ω

Step 4) Check the blower thermostat, belt switch, centrifugal switch and motor overload

Step 5) Check Main PCB Board and Motor → Replace a main PCB board if it is not 120v from Main PCB Board

Yoder Loop Leak Protocol

Before isolating a Yoder Loop or even tapping into a sealed system you need to have gathered the below readings from the unit....

- Temperature inside the unit.
- Compressor Amp Draw.
- Compressor Voltage.
- Evaluate Frost Pattern.

(And of course, you need to rule out all factors that could mimic a sealed system issue. Airflow Issues, Defrost Issues, Fan Issues, etc. Before ever tapping into a unit).

Once you tap you need to record...

- High Side Run Pressure
- Low Side Run Pressure

(It is best that the unit has been running for at least 25 minutes before gathering these pressures so that you are seeing accurate readings. Many units have a start up process where the Compressor does not run full stroke for the first 25 minutes.

This means it would be wise to contact the customer the day before or hours before you arrive to make sure the unit has been plugged in and running so you do not have to wait once in the home.)

Equalization Test

(needed if pressures could sway to leak or restriction. A restriction after the drier can mimic high side leak pressures)

- An equalization test can be done to rule out restrictions. Pressures should equalize in under 10 minutes if there are no restrictions.
- Once the unit equalizes, record what pressure it equalizes at. (Note that Ambient and internal temperatures will affect what PSI the pressures will equalize at).

All the above should be recorded in your notes in GSFS for all sealed system repairs. In the case that you need to contact TCC the agent will need the information above to properly diagnose with you.

If the above readings do not point toward High Side Leak then troubleshoot for low side leak, restriction, inefficient compressor, or whatever the case may be.

If the above readings point toward High Side Leak you will need to isolate your high side components and check for leaks.

- Pressurize the whole high side to 200psi and bubble test all visible joints and leak points. (Joints at Compressor, Condenser, Drier).
- If you do have a drop in pressure on the high side and can find no leaks at any joints then isolate the condenser and test it by itself.
- 3) If no joints on the High Side are leaking and the condenser is not leaking, then the Yoder can be tested.

□ <u>To properly test the Yoder Loop(1/3)</u>

- Yoder needs to be fully isolated by itself. This means removing the drier and cutting the yoder loose on the condenser side above the factory connection.
- Close off one side of the yoder loop.
- Attach one gauge to the other side of the yoder loop. There is no need to hook up gauges to both sides of the yoder, this increases your chances of equipment failure mimicking a yoder leak.

Right side are examples of Proper isolations and what will be expected to be seen by the TCC agent when running telepresence.







□ <u>To properly test the Yoder Loop(2/3)</u>

Right side are examples of improper isolations that need the driers and factory connection points removed because they sometimes leak and will trick you into thinking the yoder is bad. The goal is to eliminate all possible leak points outside of the yoder loop.





Above Example shows multiple potential leak points and why the drier needs to be removed for testing


□ <u>To properly test the Yoder Loop(3/3)</u>

Once you have fully isolated the Yoder Loop by itself, Pressurize up to 300PSI and watch for a drop in pressure. If there is a drop in pressure you need to take bubble solution and spray your connections and possible leak points where you are connected to the yoder.



Technician connection leaking

Also, make sure your gauges are not leaking. The seals need to be replaced regularly and your gauges need to be pressure tested from time to time to make sure they are not slowly leaking and mimicking leaks.





If all the above has been done and you feel the yoder loop is leaking, you will need to call into TCC with your readings and findings. Telepresence will need to be ran so the TCC agent can verify that the yoder is the issue.

Refrigerator SVC Bulletins



Service Bulletin


Product : Refrigerator Bulletin # : CNZ202300111-01 Release Date : 2023.08.31


			Air Fi	lter Cove	r part o	change for Stand	lardizatio	on		
Bulletin Type	: Qua	lity 🔄	Parts 🗹 Others	; 🗌		Applicable on	y with sy	mptoms 🖌		with every repair
Applicable fo	r Serial Nur	nber : 206KR*~	-306KR* (2022.06~202	3.06)						
Applicable fo	r models :	SalesModel LRYXC2606D LRYXC2606S LRYKC2606S LCFC26XSS LRFOC2606S LRFOC2606S LRFGC2706S LRFGC2706S LLFGC2706S LLFGC2706S LLFGC2706S LLFGC2706S LLFGC2706S LRFLC2706S LRFLC2706S	Model.Suffix GR-L268BKNH.ASBC GR-L268BSNH.ASTC GR-X268BSNH.ASTC GR-L268FSTH.ASTC GR-G268FSRH.ASTC GR-V278FSRH.ASTC GR-V278FSRH.ASTC GR-V278HSRH.ASTC GR-V278HSRH.ASTC GR-V278HSRH.ASTC GR-W278GSRH.ASTC	NA0 LR NA0 LR NA0 LC NA0 LR NA0 LR NA0 LR NA0 LR NA0 LL NA0 LL NA0 LL NA0 LF	YXC26 YXC26 YKC26 FC263 FOC26 FC27 FGC27 FGC27 FGC27 FGC27 RFLC27	Model.Suffix 606D.ASBCNA0 606S.ASTCNA0 606S.ASTCNA0 606S.ASTCNA0 606S.ASTCNA0 706S.ASTCNA0 706S.ASTCNA0 706S.ASTCNA0 706S.ASTCNA0 706S.ASTCNA0 706S.ASTCNA0 706S.ASTCNA0				
Symptoms	Air Filter (L into the air t	T120F) does not f îilter cover	fit		<u> </u>	Front View (Sam	<u>e)</u>	As Is Slanted	Back Vie	w <u>To Be</u> Square
Cause	Air Filter Sta Affected par	Indardization ts : Air filter cover	, Duct assembly	Picture	(Open	Fresh Air Filter	Carry			



1. Replace with the new parts

2. Current and New (Visual / Part number & Name etc)







1. Replace with the new parts

2. Current and New (Visual / Part number & Name etc)

Na	SVC	Description	Demoril		
No	Location	Description	Current	New	Remark
			ADJ75352113	ADJ75352123	Change
2	120A	Duct Accombly Multi	ADJ75352116	ADJ75352124	Change
ა	IZUA	Duct Assembly,Multi	ADJ75352117	ADJ75352125	Change
			ADJ75352118	ADJ75352126	Change

Part Interchangeable :		Current Part	New Part	Scrap Current Part in LG Warehouse :	Yes 🖌	No	
	Current Product	No	Yes				
	New Product	No	Yes				

Extended Warranty		
This service is covered by an extended warranty Ye	es	No 🖌
- If Yes, Parts for () years and Labor for () years by LG.		
- If No, Parts and labor are charged to the customer if outside warranty	y period.	
The warranty period, including any extended warranty above, starts from the original date of pur	urchase.	

• The information is available through "https://gsfs-america.lge.com" with a valid ID.

• The information is intended for experienced technicians, not for customer .

• The information is subject to change or update without notice.

Washing Machine SVC Bulletins



Service Bulletin

Product : Dryer Bulletin # : DFZ202300090-01 Release Date : 2023.05.15

[Others] 2	24inch/27inch Drye	er Roller SVC (Guide				
Bulletin Typ	be : SVC Notice 🔲 F	Parts 🗹 Othe	rs 🗌	A	pplicable only with s	symptoms 🗹	with every repair
Applicable f	for Serial Number : Eve	ery (Serial Numb	er:%%%	%%%%%%)			
Applicable f Heat pump Di							
Symptoms	Roller Noise Black lines are on the clot		Distant	- Black Lin	e Worn -	- Press	ed Distorted -
Cause	Bad Roller (* pressed / dis		Picture				
1. Repair In	struction						
2) If you chee ** In the past, When only c	ner call a service with detachin ck that the roller are worn, pre- only one part was supplied, but one roller is replaced, the roller o and New (Visual / Par	essed or distorted, re now two rollers are sup on the other side is often	place the roll oplied as a set n damaged an	er. to prevent re-ser	vice.		
SVC	Description		P/No.		Visual		
Location	Description	Before		After	Visual	- Electron	NAME I
B127	24inch Roller Assembly	4581EL3001J 4581EL2002H 4581EL3001M	A	GM75510754	Refer the right side picture	00	SVC PART
K250	27inch Roller Assembly	4581EL2002H	A	GM75510755	(In Pair)		and the second second

Service Bulletin

Product : Dryer Bulletin # : Release Date : 2023.05.15

f

Part Interchangeab	le :			Scrap Current Part in LG Warehouse : Yes 🗌 No 🗹
		Current Part	New Part	
	Current Product	0	0	
	New Product	0	0	
Extended Warranty	,			
This service is co	vered by an extended	l warranty	Yes	No
- If Yes, Parts	s for () years and L	abor for ()	years by LG.	
- If No, Parts	and labor are charged	to the custom	er if outside	warranty period.
• The warranty period, incl	uding any extended warrar	nty above, starts fro	om the original	ate of purchase.

•The information is intended for experienced technicians, not for customer .

• The information is subject to change or update without notice.

Dishwasher SVC Bulletins



Service Bulletin

Product : Dishwasher Bulletin # : CDZ202300003-01 Release Date : 2023.07.24

	[Quality_Common] IE Error_Check and Repair guide								
Bulletin Type	Bulletin Type: SVC Notice 🗹 Parts 🗌 Others 🦳 Applicable only with symptoms 🗹 with every repair								
Applicable f	or Serial Nu	mber : All							
Applicable f	or models	Common	DF***** / DU***** / DU5**** / SKSDW*****/						
		LGEAP	XD3***** / XD4***** / XD5*****						
		LGEME/LGEDF	XD6*** / XD7*** / XD8*** / XD9***						
Symptoms	IE Error (W	/ater inlet p	roblem)	Picture					
Cause	Refer to re	pair instruc	tion	Ficture					


Repair Instruction

IE errors occur when water is not supplied to the product or when water is not detected

Error detecting period	Error sensing condition	Detailed action	Possible Cause	Solution
Water Supply Section	 30Hz of water supply frequency detection for more than 30seconds If the water supply does not meet the set value within 10 minutes The washing motor does not detect the water supplied normally 	(Drain 30s + Pause) × 4times	 The water supply valve or tap is locked The water supply hose is kinked or frozen The water pressure is too high or too low The filter on the water supply hose is clogged The valve of water supply hose is not working The voltage is too low The connector of water supply hose is disconnected The impeller of water jacket is stuck The hall sensor of water jacket is not working The solenoid valve of water jacket is defective Incorrect detection of washing motor Main PCB is defective 	 Open the water supply valve or tap Adjust the water supply hose Check the water pressure (0.05~0.6Mpa) Cleaning the filter of water supply hose Replace the water supply hose Check the voltage (220V ± 10%) Connect the connector of water supply hos Replace the water jacket Replace the solenoid valve or water jacket Replace the washing motor Replace the main PCB


Service Bulletin

Product : Dishwasher Bulletin # : CDZ202300007-01 Release Date : 2023.07.17



Service Bulletin

Product : Dishwasher Bulletin # : CDZ202300007-01 Release Date : 2023.07.17



Service Bulletin

Product : Dishwasher Bulletin # : CDZ202300007-01 Release Date : 2023.07.17

Location Description (Factory model name) Current New Current New Image: Im	SVC		Model Name	F	/No	Visual (Version)	
rt Interchangeable : no		Description	(Factory model name)	Current	New	Current	New
t Interchangeable : no Scrap Current Part in LG Warehouse : Yes No							
tended Warranty	t Interch	angeable : no			Scrap Current Pa	rt in LG Warehouse : Y	′es 🗌 No 🔽

• The warranty period, including any extended warranty above, starts from the original date of purchase.

• The information is intended for experienced technicians, not for customers.

• The information is subject to change or update without notice.

Cooking(Gas Oven) SVC Bulletins



Service Bulletin

Product : Gas Oven Bulletin # : CVZ202300002-01 Release Date : 2023.1/20

[SVC Guide] Replace the cooktop burner orifices(nozzles)						
Bulletin Type : SVC Notice 🗸 Parts Others Applicable only with symptoms 🖌 with every repair						
Applicable for Serial Number : All						
SKS	For models _6336*, LSGL6335*, LSGL6337*, LTGL6937*, LSGS GR360*, SKSGR480*, SKSDR360*, SKSDR480* SGL6335*, LSGS6338*, LSGL5831* LSGL5833*, Sk	·				
Symptoms Replace the cooktop burner orifices(nozzles)						
Cause	 Gas Conversion (LP ↔ LN) When the gas type supplied to the customer's House and the product gas type are different. * The range leaves the factory set for use with LN(natural gas). If the orifices are need to be replaced. In case of the nozzle is deformed or damaged or if replacement is required for other reasons. 	Picture	N/A			

Service Bulletin

Product : Gas Oven Bulletin # : CVZ202300002-01 Release Date : 2023.1/20

1. Repair Instruction

When Converting the Gas, proceed according to the contents of 'CONVERSION KITS'. Also, Please be sure to check the following 'Note' below.

Conversion Kit







 When converting to LP gas, keep 'CONVERSION KITS' in case you need to convert back to natural gas.
 And save the orifices removed from the appliance for future use.

[Note]

1) To convert the Outer Orifice of the Dual Burner, using a 9/32" or 7mm box-end wrench. (The 6 point box-end wrench is recommended.) % When using an open-end wrench, the nozzle may be damaged or deformed as 'Defect Case' below, so use a box-end wrench.





(Defect Case)



12 point



Service Bulletin


Product : Gas Oven Bulletin # : CVZ202300002-01 Release Date : 2023.1/20

1. Repair Instruction


[Note]


2) When removing the orifices, proceed with the burner body fixed to the cooktop with screws.

OK



NG × Do not remove the orifices when the cooktop is removed or the burner body is not secured. (The pipe may be damaged as shown in the 'Defect Case' below.)





(Defect Case)



Service Bulletin

Part Interchangeable:		Current Part	New Part	Scrap Current Part in LG Warehouse : Yes 🗌 No 🗸	
5	Current Product	Yes	Yes		
	New Product	Yes	Yes		
Extended Warranty	Extended Warranty				
This service is covered by an extended warranty Yes No					
- If Yes, Parts for () years and Labor for () years by LG.					
- If No, Parts and labor are charged to the customer if outside warranty period.					
• The warranty period, including any e	extended warranty a	bove, starts from	n the original date	te of purchase.	

• The information is available through "https://gsfs-america.lge.com" with a valid ID.

• The information is intended tor experienced technicians, not for customer .

• The information is subject to change or update without notice.

Service Bulletin


Product : Oven Bulletin # : CVZ202300014-01 Release Date : 23.06.09

	Part replacement Water Tank an	d Steam Heat	er	
Bulletin Typ	e : SVC Notice 🖌 Parts 🗌 Others 📄 🛛 Applicab	le only with sym	ptoms 🗌 with every repair 🖌	
Applicable f	or Serial Number : 010KM ~ 208KMxxx			
	or models : DR480SIS, SKSDR480GS KSDR480SIS			
Symptoms 'The Water level is low. Refill the reservoir.' is Displayed, but Water reservoir is full The water level is low. Refill the reservoir. Picture Picture Picture		The water level is low. Refill the reservoir.		
Cause	Parts variance and molding Condition			

1. Repair Instruction

1) If 'Water reservoir is low' is Displayed, but Water reservoir is full. Then change two parts that is marked below table.

SVC Location	Description	P/No.
3022	Heater Assembly	AEG74450005
3731	Tank Assebmly,Water	AJL74692007



Service Bulletin

Product : Oven Bulletin # : CVZ202300014-01 Release Date : 23.06.09

SVC Location	Description	P/No	Visual	
SVC Location	Description	TINO	Before	After
3022	Heater Assembly	AEG74450005	Image: With the second seco	Same Heater Assembly MFG Date : 2022.08
3731	Tank Assebmly,Water	AJL74692007		Same

Service Bulletin

Product : Oven Bulletin # : CVZ202300014-01 Release Date : 23.06.09

Part	Part Interchangeable:			Scrap Current Part in LG Warehouse : Yes 🗸 No 🗌		
		Current Part	New Part			
	Current Product	No	Yes			
	New Product	No	Yes			
	nded Warranty					
-	This service is covered	l by an extended wa	rranty Yes	No 🗸		
	- If Yes, Parts for () years and Labor for () years by LG.			G.		
	- If No, Parts and labor are charged to the customer if outside warranty period.					
• The	warranty period, including a	any extended warranty al	pove, starts from the orig	nal date of purchase.		

• The information is intended tor experienced technicians, not for customer .

• The information is subject to change or update without notice.

TV SVC Bulletins



Service Bulletin

Product: OLED TV Bulletin #: GLZ202300028-01 Release Date: 06/23/2023

OLED77M3/83M3/97M3 No video issue / Keep display guide image issue Service Action

Bulletin Type	e: SVC Notice 🖌 Parts 🗌 Others 🗌 🖌	Applicable only with syn	nptoms 🗹	with every repair	
Applicable for	or Serial Number: MFD 2023.06				
Applicable for	or models: OLED77M3/83M3/97M3				
Symptom 1					
Cause 1	The customer may not see video, as the TV display is under process.	OLED pixel compensation	Picture		
Symptom 2	The TV screen doesn't automatically power off even when t	he Box power is unplugged.		0	
Cause	SW behavior malfunction of TV display internal Micom.		Picture		
1. Symptoms					
Category	Case1 Case2				
Symptom	No video or image on TV screen Keep display guide image issue				
Reproduce procedure	 ① Power off by magic remote and disconnect Box power ② Plug Box power cord and power on (TV is under pixel refresher process) ③ There's no video or image on TV screen (TV is still under pixel refresher process and the process is not done) 	 Let Box unplugged and wait more t TV display would turn off after a mo TV on by remote controller (the B The TV screen keep display guide i (TV display should turn off after 5 	oment Box is still unplugge image	Instart WEBUSZZ Serial Number : SKJY107 J) S/W Version : 00 00 00 11 Micom Version : V4.79.1 V2.13.0 Boot Version : 4,06.56/#.400.00 N/A UHD BE Version : N/A Chip Type : 022N	
Quick Fix	Unplug and plug TV display power cord	Plug Zero connect Box power cord a	and TV on by remot	te controller	
Primary Solution	y Solution Perform Micom FW update by using USB update file (Follow symptoms occur at specific version of Micom (same or less than V2.12.0))				
2. Repair Gui	de				

• Perform Micom FW update by using USB update file (Micom FW is not supported by network update)

See attached zip file

- Update File: o22n-global-mdisplay-micom_v2130_usb_V3_SECURED.epk
- Copy attached update file the folder named "LG_DTV" under USB memory root folder and plug it to Box.

Service Bulletin

Product: OLED TV Bulletin #: GLZ202300028-01 Release Date: 06/23/2023

- 4. After service SW version check the following;
- Micom version (second section): check V2.13.0.



Part Interchangeable	e :	_	Scrap Current Part in LG Warehouse: Yes 🗌 No 🗹	
		Current Part	New Part	
	Current Product	-	-	
	New Product	-	-	

Extended Warranty					
This service is covered by an extended warranty Yes No 🖌					
- If Yes, Parts for () years and Labor for () years by LG.					
- If No, Parts and labor are charged to the customer if outside warranty period.					
 The warranty period, including any extended warranty above, starts from the original date of purchase. 					

- The information is available through "https://gsfsplus-america.lge.com" with a valid ID.
- The information is intended for experienced technicians, not for customer .
- The information is subject to change or update without notice.